



ESTABLISH THE TWO REFERENCE (0,0) LINES, THEN USE THESE DIMENSIONS SHOWN TO CHECK POINTS ON THE PERIMETER.

USE RADII AND LINEAR DIMENSIONS AS CROSS CHECKS FOR ESTABLISHING THE CORRECT CURVE OF THE FOUNDATION